

BD Phoenix™ M50

Date of Critical or Security Patches: June 2021

Critical Security Patches: October 2020 – March 2021

Microsoft® & Third-Party Patches for Windows 10 1507 LTSB

BD has identified patches from Microsoft® that have been identified as critical or important security related updates thru March 2021. These patches were not found to adversely affect BD products and will be applied according to customers' service agreement.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

Patch Name	Patch Description	Patch ID	Notes
Security Update	This security update makes improvements to Secure Boot DBX for the supported Windows versions	KB4535680	
Adobe Security Update	This update removes Adobe Flash Player that is installed on any of the Windows operating systems.	KB4577586	
Security Update	<ul style="list-style-type: none">Addresses an elevation of privilege security vulnerability documented in CVE-2021-1640 related to print jobs submitted to "FILE:" ports. After installing Windows updates from March 9, 2021 and later, print jobs that are in a pending state before restarting the print spooler service or restarting the OS will remain in an error state. Manually delete the affected print jobs and resubmit them to the print queue when the print spooler service is online.Security updates to the Windows Shell, Windows User Account Control (UAC), Windows Fundamentals, Windows Core Networking, the Microsoft Graphics Component, Internet Explorer, Microsoft Edge Legacy, and Windows Media.	KB5000807	
Servicing Stack Update for Windows 10 version 1507.	This update makes quality improvements to the servicing stack, which is the component that installs Windows updates. Servicing stack updates (SSU) makes sure that you have a robust and reliable servicing stack so that your devices can receive and install Microsoft updates.	KB5001079	1



Notes:

- 1. Service Stack update KB5001079 should be installed prior to all other updates.**