Security Patches:
BD MAX™

June 2023

BD has identified patches from Microsoft® that have been identified as critical or security related through April 2023. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Security update for Secure Boot DBX	This security updates makes improvements to Secure Boot DBX.	KB5012170	
Servicing stack update for Windows 10 1809	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5023788	This update must be installed prior to all other updates
Windows 10 1809 Cumulative security update.	Addresses security issues for the Windows 10 operating system.	KB5025228	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD