Security Patches:
BD Phoenix™ M50

December 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for October 2023. These patches were found to adversely affect the BD Phoenix M50 and should not be applied according to customers' service agreements.

Microsoft® patches

Patch name	Description	Patch ID	Notes
Windows 10 1507 Cumulative security update.	Addresses Critical security updates for the Windows operating system.	KB5029259	This update should NOT be installed on the BD Phoenix M50.
Windows 10 1507 Cumulative security update.	Addresses Critical security updates for the Windows operating system.	KB5030220	This update should NOT be installed on the BD Phoenix M50.
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5023787	Must be installed before other updates.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD