Security Patches:
BD Phoenix™ M50

June 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for March 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5011569	
Windows 10 1507 Cumulative security update.	Addresses an issue that prevents printing from operating properly for some low integrity process apps. Addresses an issue that causes Windows to go into BitLocker recovery after a servicing update. Addresses an issue that fails to write Active Directory (AD) attributes properly during a Lightweight Directory Access Protocol (LDAP) modify operation of multiple attributes.	KB5011491	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD