Security Patches:
BD Pyxis™ MedStation™ 3500

March 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for March 2023 will not install on BD Pyxis™ MedStation™ 3500.

The patches include updates that may adversely affect BD Pyxis™ MedStation™ 3500. These patches will not be and should not be installed on BD Pyxis™ MedStation™ 3500 at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2023-03 Security Only Quality Update for Windows Embedded Standard 7 for x86-based Systems	This update makes improvements for the following: • The Local Security Authority Subsystem Service (Lsass.exe) might stop responding after System Preparation (sysprep) is run on a domain-joined device. • By order of the Mexican government in October 2022, the United Mexican States will not observe daylight saving time (DST) in 2023.	KB5023759	1
2023-03 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems	This cumulative security update contains improvements that are part of update KB5022872 (released February 14, 2023). This update also makes improvements for the following issues: • The Local Security Authority Subsystem Service (Lsass.exe) might stop responding after System Preparation (sysprep) is run on a domain-joined device. • By order of the Mexican government in October 2022, the United Mexican States will not observe daylight saving time (DST) in 2023.	KB5023769	1

Note:-

1. Due to environment issue patches were unable to be validated this month.

BD has identified patches from Microsoft® that have been identified as critical or security related for March 2023 will not install on BD Pyxis™ MedStation™ 4000.

The patches include updates that may adversely affect BD Pyxis™ MedStation™ 4000. These patches will not be and should not be installed on BD Pyxis™ MedStation™ 4000 at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
Windows Malicious Software Removal Tool - v5.111	The Windows Malicious Software Removal Tool (MSRT) helps remove malicious software from computers.	KB890830	1
2023-03 Security Only Quality Update for Windows Server 2008 for x86-based Systems	This update makes improvements for the following issues: ▪ The Local Security Authority Subsystem Service (Lsass.exe) might stop responding after System Preparation (sysprep) is run on a domain-joined device. ▪ By order of the Mexican government in October 2022, the United Mexican States will not observe daylight saving time (DST) in 2023.	KB5023754	1
2023-03 Security Monthly Quality Rollup for Windows Server 2008 for x86-based Systems	This cumulative security update contains improvements that are part of update KB5022890 (released February 14, 2023).	KB5023755	1

Note:-

1. Due to environment issue patches were unable to be validated this month.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com