Security Patches:
BD **Pyxis™ Anesthesia ES**

Sep 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for September 2022 will not install on BD Pyxis™ Anesthesia ES.
The patch includes updates that may adversely affect Pyxis™ Anesthesia ES.
 This patch will not be and should not be installed on BD Pyxis™ Anesthesia ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-09 Servicing Stack Update for Windows Embedded Standard 7 for x86-based Systems	This update makes quality improvements to the servicing stack, which is the component that installs Windows updates. Servicing stack updates (SSU) makes sure that you have a robust and reliable servicing stack so that your devices can receive and install Microsoft update**s.**	**KB5017397**	1
2022-09 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems	This cumulative security update contains improvements that are part of update KB5016676 (released August 9, 2022) and includes key changes for the following issue: This update contains miscellaneous security improvements to internal OS functionality. No specific issues are documented for this release.	**KB5017361**	1

Note:
1. PCI is not getting installed on PAS ES 2008R2- 1.4.4.1.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD has identified patches from Microsoft® that have been identified as critical or security related for September 2022 will not install on BD Pyxis™ CIISafe
The patch includes updates that may adversely affect Pyxis™ CIISafe.
 This patch will not be and should not be installed on BD Pyxis™ CIISafe at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only applies to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-09 Servicing Stack Update for Windows 10 Version 1607 for x64-based Systems	Install this update to resolve issues in Windows. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article for more information. After you install this item, you may have to restart your computer.	KB5017396	1
Windows Malicious Software Removal Tool x64 -v5.105	The Windows Malicious Software Removal Tool (MSRT) helps remove malicious software from computers. Use this tool to find and remove specific prevalent threats and reverse the changes they have made.	KB890830	1

2022-09 Cumulative Update for Windows 10 Version 1607 for x64-based Systems	**A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. After you install this update, you may have to restart your system.**	[KB5017305](KB5017305)	**1**

Note:

1. Patches not getting downloaded and installed on Win 10 Physical CIISafe Legacy devcie.