Security Patches:
BD **Pyxis™ Med Station ES**

June 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2022 will not install on BD Pyxis™ Med Station ES.
The patch includes updates that may adversely affect Pyxis™ Med Station ES. This patch will not be and should not be installed on BD Pyxis™ Med Station ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-06 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems.	This cumulative security update contains improvements that are part of update KB5014012 (released May 10, 2022) and includes new improvements for the following issue: Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	**KB5014748**	1
2022-06 Security Only Quality Update for Windows Embedded Standard 7 for x86-based Systems.	This security-only update includes new improvements for the following issue: Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	KB5014742	1

Note:
1. Server application is not getting launch on Med ES Server 2008R2- 1.4.4.1, displays a run time error.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

Security Patches:
BD **Pyxis™ Anesthesia ES**

June 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2022 will not install on BD Pyxis Anesthesia ES. The patch includes updates that may adversely affect BD Pyxis Anesthesia ES. This patch will not be and should not be installed on BD Pyxis™ Anesthesia ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-06 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems.	This cumulative security update contains improvements that are part of update KB5014012 (released May 10, 2022) and includes new improvements for the following issue: Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	**KB5014748**	1
2022-06 Security Only Quality Update for Windows Embedded Standard 7 for x86-based Systems.	This security-only update includes new improvements for the following issue: Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	KB5014742	1

Note:
1. Server application is not getting launch on Med ES Server 2008R2- 1.4.4.1, displays a run time error

Security Patches:
BD Pyxis™ MedStation™ 4000
June 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2022 will not install on BD Pyxis™ MedStation™ 4000.

The patches include updates that may adversely affect BD Pyxis™ MedStation™ 4000. These patches will not be and should not be installed on BD Pyxis™ MedStation™ 4000 at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-06 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems	This cumulative security update contains improvements that are part of update KB5014012 (released May 10, 2022) and includes new improvements for the following issue: Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	KB5014748	1
2022-06 Security Only Quality Update for Windows Embedded Standard 7 for x86-based Systems	This security-only update includes new improvements for the following issue: Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	KB5014742	1

Note:

1. MED4000 Win7 device is unable to connect to VPN, due to which system is unable to Fetch and Validate above mentioned patches.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

Security Patches: BD Pyxis™ Supply

June 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2022 will not install on BD Pyxis™ Supply.

The patch includes updates that may adversely affect Pyxis™ Supply. This patch will not be and should not be installed on BD Pyxis™ Supply at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-06 Security and Quality Rollup for .NET Framework 2.0, 3.0, 4.6.2 for Windows Server 2008 SP2 (KB5014809)	This security update addresses an issue where a local user opening a specially crafted file could cause a denial of service condition on an affected system. For more information please see CVE-2022-30130.	KB5014809	1
2022-06 Security Only Quality Update for Windows Server 2008 for x86-based Systems (KB5014743)	This security-only update includes new improvements for the following issue: • Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	KB5014743	1
2022-06 Security Monthly Quality Rollup for Windows Server 2008 for x86-based Systems (KB5014752)	This cumulative security update contains improvements that are part of update KB5014010 (released May 10, 2022) and includes new improvements for the following issue: • Printing to a NUL port from a Low Integrity Level (LowIL) process application could cause printing failures.	KB5014752	1

| Windows Malicious Software Removal Tool x64 - v5.102 | The Windows Malicious Software Removal Tool (MSRT) helps remove malicious software from computers. Microsoft releases the MSRT on a monthly cadence as part of Windows Update or as a standalone tool. Use this tool to find and remove specific prevalent threats and reverse the changes they have made. | KB890830 | 1 |

Note:
1. Due to environment issue patch was unable to be validated this month.