Security Patches:
BD Viper™ LT

February 2024

BD has identified patches from Microsoft® that have been identified as critical or security related through December 2023. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed first.
Windows 10 1809 Cumulative security update.	This update addresses security issues of the operating system.	KB5033371	
Windows 10 1809 Cumulative update for .NET Framework 3.5 and 4.8.	This update addresses security bypass and elevation of privilege vulnerabilities.	KB5031990	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD