

Security Patches: BD Accuri™ System

January 2023

BD Biosciences - BD Accuri™ C6 Plus Analyzer

Microsoft™ and Third-Party Patches: January 2023

BD has identified patches from Microsoft™ that have been identified as critical or security related for January 2023. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

Microsoft™ patches: Windows™ 10 Enterprise LTSC

Patch name	Description	Patch ID	Notes
January 2023 Monthly Cumulative Updates	Security and quality updates for Microsoft™ Windows™ 10 Enterprise (LTSC) v1809	KB5022286	1, 2

Microsoft™ patches: Windows™ 10 Professional

Patch name	Description	Patch ID	Notes
January 2023 Monthly Cumulative Updates	Security and quality updates for Microsoft™ Windows™ 10 Professional v22H2	KB5022282	1, 2



Notes

1. Patches may require the system to reboot.
2. For further information from Microsoft regarding CVEs covered by the January Security updates, please refer to the following link – <https://msrc.microsoft.com/update-guide/releaseNote/2023-Jan>

For Research Use Only. Not for use in diagnostic or therapeutic procedures.

Class 1 Laser Product.

BD Biosciences, San Jose, CA, 95131, U.S.
877.232.8995

bd.com

BD, the BD Logo and Accuri are trademarks of Becton, Dickinson and Company or its affiliates.
All other trademarks are the property of their respective owners. © 2023 BD. All rights reserved. BD-85675 (v1.0) 0423

