

Security Patches: BD Assurity Linc™

September 2022

BD has identified patches from Microsoft® that have been identified as critical or security related through June 2022 for the BD Assurity Linc™ on Windows LTSC 1809. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

Microsoft® patches

Patch name	Description	Patch ID	Notes
Cumulative security update for .NET Framework 3.5 and 4.7 for Windows 10 1809	This security update addresses an issue where a local user opening a specifically crafted file could cause a denial of service condition on an affected system.	KB5013641	
Security update for Windows 10 1809.	This security update addresses an elevation of privilege vulnerability.	KB5014692	
Security update for Secure Boot DBX Windows 10 1809	This security updates makes improvements to Secure Boot DBX for the supported Windows version.	KB4535680	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

