Security Patches: BD Data Agent

May 2022

BD has identified patches from Microsoft[®] that have been identified as critical or security related for May 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

Microsoft[®] patches

Install this update to resolve issues in Windows. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article for more information. After you install this item, you may have to restart your computer.

KB5014026

Applicable on CIISafe and PLX.



Windows Malicious Software Removal Tool x64 - v5.101 (KB890830) After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product.

KB890830

Applicable on CII Safe, Infusion and PLX.

2022-05 Cumulative Update for Windows 10 Version 1607 for x64-based Systems (KB5013952) A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.

KB5013952

Applicable on CII Safe and PLX

BD, Franklin Lakes, NJ, 07417, U.S. 201.847.6800



