

Security Patches: BD EpiCenter™

September 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

Microsoft® patches

| Patch name | Description | Patch ID | Notes |
|--|--|---------------------------|---|
| .NET security update for Windows 10 1809 | This security update addresses an issue where a local user opening a specially crafted file could cause a denial of service condition. | KB5013641 | |
| Servicing stack update for Windows 10 1809 | This update makes quality improvement to the servicing stack, which is the component that installs Windows updates. | KB5005112 | This update must be installed prior to all other updates |
| Cumulative security update for Windows 10 1809 | This update addresses security issues in the Windows operating system. | KB5014692 | Devices with some Asian language packs may receive error "0x800f0982 – PSFX_E_MATCHING_COMPONENT_NOT_FOUND" Workaround: Uninstall and reinstall any recently added language packs. |

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

