

Security Patches: BD MAX™

January 2025

BD has identified patches from Microsoft® that have been identified as critical or security related through October 2024. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements. Customers should note that the BD MAX system has been updated to the Windows IOT10 1809 build from the Windows IOT 10 1607 build.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing stack update for Windows 10 1809	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed prior to all other updates
Windows 10 1809 Cumulative security update.	Addresses security issues for the Windows 10 operating system.	KB5044277	
Microsoft .NET Framework 3.5 and 4.7.2 cumulative security update.	Addresses security issues in the Microsoft .NET framework.	KB5044016	
Microsoft .NET Runtime update 3.1.32	Addresses security issues in the Microsoft .NET runtime.		Update to .NET runtime 3.1.32

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

