

Security Patches: BD MAX™

September 2025

BD has identified patches from Microsoft® that have been identified as critical or security related through July 2025. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements. Customers should note that the BD MAX system has been updated to the Windows IOT10 1809 build from the Windows IOT10 1607 build.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing stack update for Windows 10 1809	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed prior to all other updates
Windows 10 1809 Cumulative security update.	Addresses security issues for the Windows 10 operating system.	KB5063877	
Security Update for Microsoft ODBC Driver 17 for SQL Server	This driver update addresses security issues for the SQL Server database.	KB5037570	
Security Update for Microsoft OLE DB Driver for SQL Server	This driver update addresses security issues for the SQL Server database.	KB5040711	

Blacklisted patches

Security Update for SQL Server 2019 RTM CU	Addresses security that has been identified in the SQL server 2019 RTM CU	KB5063757	Do not install this patch as this crashes into the software upon installation
--	---	---------------------------	--

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

