

Security Patches: BD Phoenix™ M50

September 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for July 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5014024	
Windows 10 1507 Cumulative security update.	Addresses multiple security issues including an issue that might damage BitLocker files.	KB5015832	
Windows 10 1507 Security update for Secure Boot DBX.	This security update makes improvement to Secure Boot DBX.	KB4535680	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

