

Security Patches: BD Phoenix™ M50

August 2025

BD has identified patches from Microsoft® that have been identified as critical or security related through June 2025. These patches were not found to adversely affect the BD Phoenix M50 and can be applied according to customers' service agreements. These patches will impact the onboard operator's manual of the M50, making it illegible. The operator's manual is available online through the BD public facing website.

Microsoft® patches			
Patch name	Description	Patch ID	Notes
Windows 10 1507 Cumulative security update.	Addresses Critical security updates for the Windows operating system.	KB5060998	
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5058527	Must be installed before other updates.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

