

Security Patches: BD Pyxis™ CIISafe

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ CIISafe. The patch includes updates that may adversely affect Pyxis™ CIISafe. This patch will not be and should not be installed on BD Pyxis™ CIISafe at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only applies to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-10 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5018454	1

Note:

1. Mentioned KB didn't install on one CIISafe device for this month.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis™ CIISafe ES

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ CIISafe ES.

The patch includes updates that may adversely affect Pyxis™ CIISafe ES. This patch will not be and should not be installed on BD Pyxis™ CIISafe ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only Impact to the latest 171 Environment.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021237	1
2022-12 Cumulative Update for .NET Framework 3.5, 4.7.2 and 4.8 for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021085	1

Windows Malicious Software
Removal Tool x64 - v5.108

After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product.

[KB890830](#)

1

Note:

1. Support User is not logging into the CIISafe. (Bug: 1293817)

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches:

BD Pyxis™ Anesthesia ES

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ Anesthesia ES.

The patch includes updates that may adversely affect Pyxis™ Anesthesia ES. This patch will not be and should not be installed on BD Pyxis™ Anesthesia ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021237	1
2022-12 Cumulative Update for .NET Framework 3.5, 4.7.2 and 4.8 for Windows 10 Version 1809 for x64	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021085	1

Windows Malicious Software Removal Tool x64 - v5.108	After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product	KB890830	1
2022-12 Cumulative Update for Windows 10 Version 1607 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021235	1
2022-12 Security Only Quality Update for Windows Embedded Standard 7 for x86-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021288	1
2022-12 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021291	1

Note:

1. BD Support User and CFN app Auto login issue on PAS ES 1.6.1.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis™ Anesthesia ES

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ Anesthesia ES.

The patch includes updates that may adversely affect Pyxis™ Anesthesia ES. This patch will not be and should not be installed on BD Pyxis™ Anesthesia ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only Impact to the latest 171 Environment.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021237	1
2022-12 Cumulative Update for .NET Framework 3.5, 4.7.2 and 4.8 for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021085	1

Windows Malicious Software
Removal Tool x64 - v5.108

After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product.

[KB890830](#)

1

Note:

1. Support User is not logging into the Anesthesia.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis™ MedES Server

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ MedES Server.

The patch includes updates that may adversely affect Pyxis™ MedES Server. This patch will not be and should not be installed on BD Pyxis™ MedES Server at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Cumulative Update for Windows Server 2016 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021235	1

Windows Malicious Software
Removal Tool x64 - v5.108

After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product

[KB890830](#)

1

Note:

1. Due to BD Support User is not working in 1.6.1 Server.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis™ ES Server

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ MedES Server.

The patch includes updates that may adversely affect Pyxis™ MedES Server. This patch will not be and should not be installed on BD Pyxis™ MedES Server at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only Impact to the latest 171 Environment.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Cumulative Update for .NET Framework 4.8 for Windows Server 2016 for x64	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5020873	1
2022-12 Cumulative Update for Windows Server 2016 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021235	1

Windows Malicious Software
Removal Tool x64 - v5.108

After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product.

[KB890830](#)

1

Note:

1. Support User is not logging into the Server.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches:

BD Pyxis™ MedStation ES

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ MedStation ES.

The patch includes updates that may adversely affect Pyxis™ MedStation ES. This patch will not be and should not be installed on BD Pyxis™ MedStation ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021237	1
2022-12 Cumulative Update for .NET Framework 3.5, 4.7.2 and 4.8 for Windows 10 Version 1809 for x64	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021085	1

2022-12 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021291	1
2022-12 Security Only Quality Update for Windows Embedded Standard 7 for x86-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021288	1
Windows Malicious Software Removal Tool x64 - v5.108	After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product	KB890830	1

Note:

1. BD Support User and CFN app autologin issue on Med Station ES 1.6.1

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis™ Medstation ES

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ Medstation ES.

The patch includes updates that may adversely affect Pyxis™ Medstation ES. This patch will not be and should not be installed on BD Pyxis™ Medstation ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only Impact to the latest 171 Environment.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021237	1
2022-12 Cumulative Update for .NET Framework 3.5, 4.7.2 and 4.8 for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5021085	1

Windows Malicious Software
Removal Tool x64 - v5.108

After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product.

[KB890830](#)

1

Note:

1. Support User is not logging into the Medstation.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches:

BD Pyxis™ MedStation™ 4000

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for December 2022 will not install on BD Pyxis™ MedStation™ 4000.

The patches include updates that may adversely affect BD Pyxis™ MedStation™ 4000. These patches will not be and should not be installed on BD Pyxis™ MedStation™ 4000 at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-12 Security Monthly Quality Rollup for Windows 7 for x86-based Systems	<p>This cumulative security update contains improvements that are part of update KB5020000 (released November 8, 2022) and update KB5021651 (released November 17, 2022). This update also makes improvements for the following issues:</p> <p>By order of the Fijian government, Fiji will not observe daylight saving time (DST) in 2022. Therefore, clocks do not change by an hour at 02:00 on November 13, 2022.</p> <p>A memory leak in the Local Security Authority Subsystem Service (LSASS.exe) occurs on Windows domain controllers. This issue is known to occur after installing Windows updates dated November 8, 2022, or later.</p>	KB5021291	1

Note:

1. Windows-7 Workstation is having low disk space, due to which the above KB is getting failed.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

