

Security Patches: BD Pyxis™ MedStation™ 4000

June 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2023 will not install on BD Pyxis™ MedStation™ 4000.

The patches include updates that may adversely affect BD Pyxis™ MedStation™ 4000. These patches will not be and should not be installed on BD Pyxis™ MedStation™ 4000 at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
Windows Malicious Software Removal Tool - v5.114	The Windows Malicious Software Removal Tool (MSRT) helps remove malicious software from computers.	KB890830	1
2023-06 Security Only Quality Update for Windows Server 2008 for x86-based Systems	This update contains miscellaneous security improvements to internal Windows OS functionality. No additional issues were documented for this release.	KB5027277	1
2023-06 Security Monthly Quality Rollup for Windows Server 2008 for x86-based Systems	This cumulative security update contains improvements that are part of update KB5026408 (released May 9, 2023). This update also contains miscellaneous security improvements to internal Windows OS functionality. No specific issues are documented for this release.	KB5027279	1

Note:-

1. Patch(es) could not be verified due to system environment issues.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis CIISafe

June 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2023 will not install on BD Pyxis CIISafe.

The patches include updates that may adversely affect BD Pyxis CIISafe. These patches will not be and should not be installed on BD Pyxis CIISafe at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2023-06 Security Only Update for .NET Framework 3.5.1, 4.6.2, 4.7, 4.7.1, 4.7.2, 4.8 for Windows Embedded Standard 7 (KB5027531)	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5027531	1
2023-06 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems (KB5027275)	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5027275	1



2023-06 Security and Quality Rollup for .NET Framework 3.5.1, 4.6.2, 4.7, 4.7.1, 4.7.2, 4.8 for Windows Embedded Standard 7 (KB5027540)

A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.

[KB5027540](#)

1

2023-06 Security Only Quality Update for Windows Embedded Standard 7 for x86-based Systems (KB5027256)

A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.

[KB5027256](#)

1

Note:-

1. Patch(es) could not be verified due to system environment issues.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

