

# Security Patches: BD Totalys™ Multiprocessor

September 2022

BD has identified patches from Microsoft® that have been identified as critical or security related from January to June 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

## Microsoft® patches

Patch name	Description	Patch ID	Notes
------------	-------------	----------	-------

BD, Franklin Lakes, NJ, 07417, U.S.  
201.847.6800

**bd.com**

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.





Security update for secure boot DBX for Windows 10 1607

This security update addresses the bypass secure boot vulnerability by adding the signatures of the known vulnerable UEFI modules to the DBX.

[KB4535680](#)

Servicing stack update for Windows 10 1607

This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.

[KB5014026](#)

This update must be installed prior to all other updates

Cumulative update for .NET framework 4.8 for Windows 10 1607.

Addresses a known issue where a local user opening a specially crafted file could cause a denial of service condition.

[KB5013625](#)

Cumulative update for Windows 10 1607.

Addresses a known security issue for the Windows 10 operating system.

[KB5014702](#)

BD, Franklin Lakes, NJ, 07417, U.S.  
201.847.6800

**bd.com**

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.