

Security Patches: BD Phoenix™ M50

September 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for June 2023. These patches were found to adversely affect the BD Phoenix M50 and should not be applied according to customers' service agreements.

Microsoft® patches

Patch name	Description	Patch ID	Notes
Windows 10 1507 Cumulative security update.	Out of band update.	KB5028622	This update should NOT be installed on the BD Phoenix M50.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

