

Security Patches: BD Pyxis™ Med Station ES

March 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for March 2022 will not install on BD Pyxis Med Station ES. The patch includes updates that may adversely affect BD Pyxis Med Station ES. This patch will not be and should not be installed on BD Pyxis™ Med Station ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-03 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5011503	1
2022-03 Cumulative Update for Windows 10 Version 1607 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5011495	1

Note:

1. Due to the login issue on ES machines. These patches should not be installed.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis™ Anesthesia ES

March 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for March 2022 will not install on BD Pyxis Anesthesia ES. The patch includes updates that may adversely affect BD Pyxis Anesthesia ES. This patch will not be and should not be installed on BD Pyxis™ Anesthesia ES at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
Windows Malicious Software Removal Tool x64 - v5.99	After the download, this tool runs one time to check your computer for infection by specific, prevalent malicious software (including Blaster, Sasser, and Mydoom) and helps remove any infection that is found. If an infection is found, the tool will display a status report the next time that you start your computer. A new version of the tool will be offered every month. If you want to manually run the tool on your computer, you can download a copy from the Microsoft Download Center, or you can run an online version from microsoft.com. This tool is not a replacement for an antivirus product. To help protect your computer, you should use an antivirus product.	KB890830	1
2022-03 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5011503	1



2022-03 Cumulative Update for Windows 10 Version 1809 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5011503	1
---	--	---------------------------	---

Note:

1. Due to the login issue on ES machines. These patches should not be installed

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



Security Patches: BD Pyxis™ Supply

March 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for March 2022 will not install on BD Pyxis™ Supply.

The patch includes updates that may adversely affect Pyxis™ Supply. This patch will not be and should not be installed on BD Pyxis™ Supply at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-03 Cumulative Security Update for Internet Explorer 9 for Windows Server 2008 for x86-based systems (KB5011486)	This security update resolves vulnerabilities in Internet Explorer. To learn more about these vulnerabilities, see the Security Update Guide website.	KB5011486	1
2022-03 Security Monthly Quality Rollup for Windows Server 2008 for x86-based Systems (KB5011534)	This security update includes improvements and fixes that were a part of update KB5010384 (released February 8, 2022) and addresses the following issues: <ul style="list-style-type: none">Addresses an issue in which after the January 2022 Windows update is installed on the Primary Domain Controller emulator (PDCe), listing or modifying name suffixes routing by using Netdom.exe or "Active Directory Domains and Trusts" snap-in may fail with the following error message: "Insufficient system resources exist to complete the requested service."	KB5011534	1



2022-03 Security Only
Quality Update for Windows
Server 2008 for x86-based
Systems (KB5011525)

This security update includes quality improvements.
Key changes include:

[KB5011525](#)

1

- Addresses an issue in which after the January 2022 Windows update is installed on the Primary Domain Controller emulator (PDCe), listing or modifying name suffixes routing by using Netdom.exe or "Active Directory Domains and Trusts" snap-in may fail with the following error message: "Insufficient system resources exist to complete the requested service."

2022-03 Servicing Stack
Update for Windows Server
2008 for x86-based Systems
(KB5011942)

This update makes quality improvements to the servicing stack, which is the component that installs Windows updates. Servicing stack updates (SSU) make sure that you have a robust and reliable servicing stack so that your devices can receive and install Microsoft updates.

[KB5011942](#)

1

Note:

1. Due to environment issue patch was unable to be validated this month.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

