

Security Patches: BD Totalys™ Multiprocessor

June 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for May 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Cumulative update for .NET Framework 4.8 for Windows 10 1607	This security update addresses security issues found in Microsoft .NET	KB4585207	
Servicing stack update for Windows 10 1607	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5014026	This update must be installed prior to all other updates
Windows 10 1607 Out of band security update.	Addresses a known issue that might prevent some services from authenticating machine accounts on clients or servers.	KB5015019	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

