

|      |            |  |
|------|------------|--|
| 3    | 49000227   | Actuator Knob Assembly (Complete Assembly)   |
| 255  | TC10003065 | Actuator Knob Assembly (Componet Only)   |
| 275  | 147836-002 | Actuator Knob, (Cam Pull Rod)  |
| 271  | 321041     | Actuator Knob, (Compression Spring)  |
| 265  | TC10008324 | Actuator Knob, (Flag Shaft Interrupter)  |
| 230  | 147799-001 | Actuator Knob, (Plate Slide)   |
| 397  | 320999     | Assembly, Cable Dual End Connector   |
| 325  | TC10006400 | Barrel Clamp   |
| 342  | 147987-002 | Barrel Clamp (Bushing)   |
| 326  | 321022     | Barrel Clamp (Compression Spring)  |
| 158  | TC10004194 | Barrel Clamp (Park Position Collar) (Need to order Screw See Below)  |
| N/A  | 10014496   | Barrel Clamp (Park Position Collar NYLOK Set Screw)  |
| 335  | 147810-001 | Barrel Clamp (Potentiometer Extension Guide)   |
| 321  | 302513     | Barrel Clamp (Retaining Ring)  |
| 337  | 321155     | Barrel Clamp (Shaft Seal)  |
| 340  | 147845-002 | Barrel Clamp (Shaft Support)   |
| 365  | TC10003525 | Board, Display Assembly  |
| 360  | TC10005079 | Board, Flange Detector Sensor Assembly   |
| 395  | 147816-105 | Board, IUI Interface Assembly  |
| 15   | TC10008848 | Board, Linear Sensor Assembly  |
| 390  | TC10007651 | Board, Logic Assembly (PCA Only) Use up TC10005342   |
| 305  | 147482-104 | Board, Assy pressure sensor, 8110  |
| 8100 | 10010692   | Calibration Kit, Syringe/PCA (Complete Cal Kit)  |
| 8100 | 10010691   | Calibration Kit, Syringe/PCA (Force Sensor Spring Tool Only)   |
| 8100 | 148182-100 | Calibration Kit, Syringe/PCA (Sizers and Height Gauge Tools)   |
|      | 148180-100 | Calibration Kit, Syringe/PCA (Syringe Sizers Set only)   |
|      | 148181-100 | Calibration Kit, Syringe/PCA (Height Gauge Set only)   |
| 9    | 10010996   | Case, Front Assembly Kit (Syringe Only) This is for the old version front case with the Park Pin not the Park Collar |
| 9    | 49000218   | Case, Front Assembly New Version (Syringe Only)  |
| 406  | 147872-001 | Case, Gasket Rear  |
| 8    | 10013671   | Case, Rear Assembly Kit (Syringe Only)   |
| 310  | TC10003547 | Disk Holder, Base (Syringe Only) 4 Screws #300926)   |
| 311  | 147738-000 | Disk Holder, Flag (Syringe Only)   |
| 312  | TC10008373 | Disk Holder, Flag Spring (Syringe Only)  |
| 351  | 147882-002 | Disk Holder, Mylar Gasket (Syringe Only)   |
| 315  | 147737-002 | Disk Holder, Top (Syringe Only)  |
| 350  | 147846-000 | Flag Barrel Position   |
| 355  | 147848-001 | Flag Leaf Spring   |
| 345  | TC10007599 | Flag Seal  |
| 246  | TC10003157 | Flex Cable Retainer  |
| 250  | 10013882   | Force Sensor Assembly Kit (includes screws NYLOCK #10013293)   |
| 203  | 147815-000 | Force Sensor Seal  |

|      |            |  |
|------|------------|--|
| 10   | 147539-101 | Frame Drive Train Extrusion  |
| 380  | 147739-100 | Frame, Internal  |
| 120  | 147537-000 | Guide Rod  |
| 450  | 147795-001 | Handle, Left (Syringe Only)  |
|      | 147796-001 | Handle, Right (Syringe Only)   |
| 307  | 147975-102 | Harness, Pressure Sensor (Syringe Only)  |
| 2    | 49000213   | Housing Assy kit. (complete housing assy)  |
| 4    | 49000213   | Housing Assy kit. (lower housing carriage assy.)   |
| 385  | TC10008309 | IUI Bracket  |
| 375  | 147792-000 | IUI Bracket Strap (Ground Strap)   |
| 400  | TC10008308 | IUI Support Bracket  |
| 373  | 147851-101 | Keypad LED, Backlight Harness  |
| 2004 | 147078-100 | Kit, IUI Connector Left  |
| 2003 | 147077-100 | Kit, IUI Connector Right   |
| 2006 | 147080-100 | Latch Kit (Consists of: Latch, Latch Support, Leaf Spring and Compression Spring) (Syringe Only)                       |
| 5    | 49000225   | Kit, Lead Screw Assembly   |
| 645  | 148013-000 | Label, Patent  |
| 295  | 147741-000 | Lens Status Indicator  |
| 205  | 147814-000 | Lock Plate, Force Sensor   |
| 2    | 10010997   | Lower Housing Complete Assembly (Includes Force Sensor Board and Complete Actuator Knob Assembly) (Swap & Go Assembly) |
| 6    | 49000248   | Motor Pulley Assembly  |
| 85   | TC10008310 | Motor, (Bushing Motor Isolation)   |
| 93   | 321050     | Motor, (Rubber Grommet, Used with Motor Bushing)   |
| 461  | 321100     | O-Ring, (Lower Housing to Upper Housing)   |
| 70   | TC10008307 | Plate Bottom Frame   |
| 200  | TC10003887 | Plate, Force Sensor  |
| 398  | TC10003920 | Retainer Clip for (Cable Assy, Dual End Connector)   |
| 410  | 142794-000 | Rubber, Feet   |
| 480  | 303655     | Screw, (Board, Flange Detector Sensor Assembly)  |
| 486  | 300923     | Screw, (Board, Logic Assembly) & (Internal Frame at Bottom) & (Drive Train Assy. To Front Case) & (Disk Base Holder)   |
| 460  | 321033     | Screw, (Drive Train Extrusion Frame Bottom Plate)  |
| 474  | 10015818   | Screw, (Force Sensor NYLOCK)   |
| 488  | 301708     | Screw, (IUI Bracket) & (Internal Frame at Top)   |
| 490  | 320855     | Screw, (IUI Connector) & (Rear Case)   |
| 478  | 148225-000 | Screw, (Lower Housing to Upper Housing) & (Lock Plate, Force Sensor)   |
| 462  | 321060     | Screw, (Motor Assembly)  |
| 492  | 320851     | Screw, (Rear Case, Bottom Left) & (Latch Kit)  |
| 496  | 321035     | Screw, (Right Handle)  |
| 327  | 12278652   | Sensor Assembly, Syringe Size  |
| 396  | 806112     | Snap Rivot   |

|     |            |  |
|-----|------------|--|
| N/A | 12232252   | Technical Service Manual (Syringe/PCA)               |
| 112 | 321031     | Timing Belt  |
| 281 | 147093-100 | Tubing MED Silicon, 10 feet                          |
| 285 | TC10007851 | Upper Housing (4 Screws #321062 & 4 O-Rings #321100) |
| 491 | 320729     | Washer, (Rear Case)                                  |
| 494 | 320167     | Washer, (Rear Case, Bottom Left)                     |