CYBERSECURITY ASSURANCE PROGRAM CERTIFICATE

Certificate Number: ULCAP_139

Date of Issue: 2023-07-20 **Date of Expiration:** 2024-07-21

Certificate Holder: Becton Dickinson and Company

1 Becton Drive, Franklin Lakes New Jersey, 07417 United States

Certified Product: BD Synapsys

Model: N/A

Software Version: v5.20 **Hardware Version:** N/A

Standard: UL 2900-2-1, First Edition including revisions through January 30,

2023.

NIST Vulnerability Database Date: 2023-07-06

Test Report Number: 4790815060-001

This is to certify that representative sample(s) of the Product described herein have been investigated and as of the date of testing, found in compliance with the Standard(s) indicated on this Certificate. UL does not provide any representation or guarantee that all security vulnerabilities or weaknesses will be found or that the product will not be vulnerable, susceptible to exploitation, or eventually breached. The designated Certificate Holder is entitled to market the Product in accordance with the UL Global Services Agreement and Cybersecurity Assurance Program Service Terms. This Certificate shall remain valid until the indicated Expiration Date unless terminated earlier in accordance with the Service Agreement or if the referenced Standard is amended or withdrawn. This Certificate in and of itself does not authorize the Certificate Holder to use any UL trademarks on the Certified Product. UL trademarks may only be used if the Certified Product is also covered under the applicable UL mark program(s).

David Magri Program Manager

Conformity Assessment Programs Office

UL LLC 333 Pfingsten Road Northbrook, IL, 60062, USA www.ul.com



Conditions of Certificate

The following conditions must be met for the product to continue to be in compliance with this certificate:

- 1. Software updates are to be performed in accordance with BDDSSGFS7406 Synapsys Service Manual.
- 2. Only the locally hosted HTTPS server is in scope of this certificate.
- 3. The server is to be housed in a physically access controlled environment and maintained under facility security policies. BD recommended security configurations are expected to be followed, post installation.
- 4. This certificate does not include Remote Support Services such as remote communication and features enabled for the support engagements.

UL LLC 333 Pfingsten Road Northbrook, IL, 60062, USA www.ul.com

