

Security Patches: BD BACTEC™ FX

December 2025

BD has identified patches from Microsoft® that have been identified as critical or security related through October 2025. These patches were found to adversely affect BD products and will not be applied according to customers' service agreements. An update to the anti-malware software provisioned in BD BACTEC FX was also validated recently and can be applied by BD trained service engineers.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Windows 10 1607 Cumulative Security update.	Addresses several security enhancements for the Windows operating system.	KB5066836	This patch should not be installed, as it may cause the software to crash during installation.
Windows 10 1607 Cumulative Security update.	Addresses security fixes and quality improvements for the Windows operating system.	KB5065427	This patch should not be installed, as it may cause the software to crash during installation.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

