

# Security Patches: BD BACTEC™ FX40

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related through October 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

## Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	<a href="#">KB5017396</a>	Must be installed before other updates.
Windows 10 1607 Cumulative security update.	Addresses several security issues for the Windows operating system.	<a href="#">KB5018411</a>	
Security update for Secure Boot DBX Windows 10 1607	This security updates makes improvements to Secure Boot DBX for the supported Windows version.	<a href="#">KB5012170</a>	

BD, Franklin Lakes, NJ, 07417, U.S.  
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

