

Security Patches: Care Coordination Engine

July 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for July 2022 will not install on CCE.

The patch includes updates that may adversely affect CCE. This patch will not be and should not be installed on CCE at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: This patch only apply to the latest supported version(s) of the BD offering.

Microsoft® patches

Patch name	Description	Patch ID	Notes
2022-07 Security Only Quality Update for Windows Server 2012 R2 for x64-based Systems.	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5015877	1
2022-07 Servicing Stack Update for Windows Server 2012 R2 for x64-based Systems	Install this update to resolve issues in Windows. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article for more information. After you install this item, you may have to restart your computer.	KB5016264	1
2022-07 Security Monthly Quality Rollup for Windows Server 2012 R2 for x64-based Systems	A security issue has been identified in a Microsoft software product that could affect your system. You can help protect your system by installing this update from Microsoft. For a complete listing of the issues that are included in this update, see the associated Microsoft Knowledge Base article. After you install this update, you may have to restart your system.	KB5015874	1



Note:

1. These available updates could not be tested on DoD environments. However these were tested successfully on VMs with OS 2012 R2.

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

