

Security Patches: BD EpiCenter™

December 2022

BD has identified patches from Microsoft® that have been identified as critical or security related for October 2022. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

Microsoft® patches

Patch name	Description	Patch ID	Notes
.NET security update for Windows 10 1809	This security update addresses an issue where a local user opening a specially crafted file could cause a denial of service condition.	KB5013641	
Servicing stack update for Windows 10 1809	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed prior to all other updates
Cumulative security update for Windows 10 1809	This update addresses security issues for the Windows 10 1809 operating system.	KB5018419	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

