

# Security Patches: BD EpiCenter™

March 2024

BD has identified patches from Microsoft® that have been identified as critical or security related through December 2023. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

## Microsoft® patches

Patch name	Description	Patch ID	Notes
Cumulative security update for Windows 10 1809	This update addresses security issues for the Windows 10 1809 operating system	<a href="#">KB5033371</a>	
Servicing stack update for Windows 10 1809	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	<a href="#">KB5005112</a>	This update must be installed prior to all other updates
Cumulative security update for Windows 10 1809	This update addresses security issues for the Windows 10 1809 operating system.	<a href="#">KB5031984</a>	

BD, Franklin Lakes, NJ, 07417, U.S.  
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

