BD EpiCenter[™]

Date of Critical or Security Patches: December 2021

Critical Security Patches: August 2021 – September 2021

Microsoft[®] & Third-Party Patches for Windows 10 1809 LTSC

BD has identified patches from Microsoft[®] that have been identified as critical or important security related updates thru September 2021. These patches were not found to adversely affect BD products and will be applied according to customers' service agreement.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

Patch Name	Patch Description	Patch ID	Notes
Servicing Stack Update for Windows 10 version 1809.	This update makes quality improvements to the servicing stack, which is the component that installs Windows updates. Servicing stack updates (SSU) makes sure that you have a robust and reliable servicing stack so that your devices can receive and install Microsoft updates.	<u>KB5005112</u>	1
Security Update	Cumulative security update for September 2021.	<u>KB5005568</u>	

Notes:

1. Service Stack update KB5005112 should be installed prior to all other updates.

