## Security Patches: BD EpiCenter™

September 2025

BD has identified patches from Microsoft<sup>®</sup> that have been identified as critical or security related through July 2025 for BD EpiCenter™ on Windows LTSC 1809. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s).

## Microsoft® patches

| Patch name   | Description   | Patch ID         | Notes   |
|--|---|------------------|---|
| Cumulative security update for Windows 10 1809                               | This update addresses security issues for the Windows 10 1809 operating system                                      | <u>KB5062557</u> |   |
| Servicing stack update for Windows 10 1809                                   | This update makes quality improvement to the servicing stack, which is the component that installs Windows updates. | <u>KB5005112</u> | This update must<br>be installed prior<br>to all other<br>updates |
| Cumulative security update for .NET framework 3.5 and 4.7.2 for Win 10 1809. | This update addresses security issues for the .NET framework in Windows.  | KB5062070        |   |
| SQL Server 2019 Security Update.   | This update addresses security issues for the SQL Server database.  | <u>KB5058713</u> |   |
| SQL Server 2019 Security Update.   | This update addresses security issues for the SQL Server database.  | KB5058722        |   |
| SQL Server 2019 Security Update.   | This driver update addresses security issues for the SQL Server database.   | KB5037570        |   |
| SQL Server 2019 Security Update.   | This driver update addresses security issues for the SQL Server database.   | KB5040711        |   |

BD, Franklin Lakes, NJ, 07417, U.S. 201.847.6800



