BD Product Security - Security Patch Recommendations

BD Biosciences Product Name: BD FACSCanto™ II Cell Analyzers

October / November / December 2021

Critical and/or Security Patches: The October 2021 security rollup/cumulative update was released on October 12, 2021. The November 2021 security rollup/cumulative update was released on November 9, 2021. The December 2021 security rollup/cumulative update was released on December 14, 2021.

Microsoft[™] and Third-Party Patches

BD has identified patches from Microsoft[™] that have been indicated as security related for the months of October, November and December. The BD products listed above have been tested with security patches from the October, November and December rollup/cumulative releases installed. The patches in these updates were not found to adversely affect operation of the listed BD products.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s). For products that are supported remotely by BD Service, patches will be applied according to customers' service agreements.

Patch Name	Patch Description	Patch ID	Notes
October 2021 Monthly Cumulative Updates	Security and quality updates for Microsoft Windows 10 Enterprise (LTSC) v1809	<u>KB5006672</u>	1,2
November 2021 Monthly Cumulative Updates	Security and quality updates for Microsoft Windows 10 Enterprise (LTSC) v1809	<u>KB5007206</u>	1,3
December 2021 Monthly Cumulative Updates	Security and quality updates for Microsoft Windows 10 Enterprise (LTSC) v1809	<u>KB5008218</u>	1,4

Windows[™] 10 Enterprise:



Windows[™] 10 Professional:

Patch Name	Patch Description	Patch ID	Notes
October 2021 Monthly Cumulative Updates	Security and quality updates for Microsoft Windows 10 Professional (SAC) v21H1	<u>KB5006670</u>	1,2
November 2021 Monthly Cumulative Updates	Security and quality updates for Microsoft Windows 10 Professional (SAC) v21H1	<u>KB5007186</u>	1,3
December 2021 Monthly Cumulative Updates	Security and quality updates for Microsoft Windows 10 Professional (SAC) v21H1	<u>KB5008212</u>	1,4

Notes

- 1. Patches may require the system to reboot.
- 2. For further information from Microsoft regarding CVEs covered by the October Security updates, please refer to the following link –

https://msrc.microsoft.com/update-guide/releaseNote/2021-Oct

3. For further information from Microsoft regarding CVEs covered by the November Security updates, please refer to the following link –

https://msrc.microsoft.com/update-guide/releaseNote/2021-Nov

4. For further information from Microsoft regarding CVEs covered by the December Security updates, please refer to the following link –

https://msrc.microsoft.com/update-guide/releaseNote/2021-Dec

BD FACSCanto[™] II Flow Cytometers are Class 1 Laser Products.

In the U.S., the BD FACSCanto[™] II Flow Cytometer is for In Vitro Diagnostic Use for up to six colors. Seven and eight colors are for Research Use Only.

In the EU, the BD FACSCanto[™] II Flow Cytometer is no longer available for sale.

BD, the BD Logo and FACSCanto are trademarks of Becton, Dickinson and Company or its affiliates. All other trademarks are the property of their respective owners. © 2022 BD. All rights reserved. BD-62197 (v1.0) 0622

