

# Security Patches: BD Pyxis™ MedStation™ 3500

May 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for May 2023 will not install on BD Pyxis™ MedStation™ 3500.

The patches include updates that may adversely affect BD Pyxis™ MedStation™ 3500. These patches will not be and should not be installed on BD Pyxis™ MedStation™ 3500 at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

## Microsoft® patches

Patch name	Description	Patch ID	Notes
2023-05 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems	This cumulative security update contains improvements that are part of update KB5025279 (released April 11, 2023). This update also makes improvements for the following issues: <ul style="list-style-type: none"><li>By order of the Islamic Republic of Iran on September 22, 2022, daylight saving time (DST) will no longer be observed and the republic will remain on Iran Standard Time UTC+03:30.</li><li>After the Windows Monthly Rollup dated on or after November 8, 2022, is installed, Kerberos constrained delegation (KCD) fails with the error message KRB_AP_ERR_MODIFIED on Read/Write Domain Controllers.</li></ul>	<a href="#">KB5026413</a>	1
2023-05 Security only Quality update for Windows Embedded Standard 7 for x86-based Systems	This update makes improvements for the following issues: <ul style="list-style-type: none"><li>By order of the Islamic Republic of Iran on September 22, 2022, daylight saving time (DST) will no longer be observed and the republic will remain on Iran Standard Time UTC+03:30.</li><li>After the Windows Security-only update dated November 8, 2022, is installed, Kerberos constrained delegation (KCD) fails with the error message KRB_AP_ERR_MODIFIED on Read/Write Domain Controllers.</li></ul>	<a href="#">KB5026426</a>	1

Note:-

1. Due to environment issue patches were unable to be validated this month.

BD, Franklin Lakes, NJ, 07417, U.S.  
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



# Security Patches: BD Pyxis™ MedStation™ 4000

May 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for May 2023 will not install on BD Pyxis™ MedStation™ 4000.

The patches include updates that may adversely affect BD Pyxis™ MedStation™ 4000. These patches will not be and should not be installed on BD Pyxis™ MedStation™ 4000 at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

## Microsoft® patches

Patch name	Description	Patch ID	Notes
Windows Malicious Software Removal Tool - v5.113	The Windows Malicious Software Removal Tool (MSRT) helps remove malicious software from computers.	<a href="#">KB890830</a>	1
2023-05 Cumulative Update for Windows Server 2016 for x64-based Systems	This security update includes quality improvements. When you install this KB: <ul style="list-style-type: none"><li>This update affects the Islamic Republic of Iran. The update supports the government's daylight saving time change order from 2022.</li><li>This update addresses an issue that affects the Key Distribution Center (KDC) service. When the service stops on a local machine, signing in to all local Kerberos fails. The error is STATUS_NETLOGON_NOT_STARTED.</li><li>This update addresses an issue that affects Microsoft Edge IE mode. The issue stops you from configuring add-ons.</li></ul>	<a href="#">KB5026363</a>	1

Note:-

1. Due to environment issue patches were unable to be validated this month.

BD, Franklin Lakes, NJ, 07417, U.S.  
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.



# Security Patches: BD Pyxis CIISafe

May 2023

BD has identified patches from Microsoft® that have been identified as critical or security related for May 2023 will not install on BD Pyxis CIISafe.

The patches include updates that may adversely affect BD Pyxis CIISafe. These patches will not be and should not be installed on BD Pyxis CIISafe at this time.

Customers that maintain patches independent of BD automated delivery should ensure these actions are not performed as the acting responsible entity in order to maintain the correct security posture of the system(s).

Note: These patches only apply to the latest supported version(s) of the BD offering.

## Microsoft® patches

Patch name	Description	Patch ID	Notes
2023-05 Security Monthly Quality Rollup for Windows Embedded Standard 7 for x86-based Systems	This cumulative security update contains improvements that are part of update KB5025279 (released April 11, 2023). This update also makes improvements for the following issues: <ul style="list-style-type: none"><li>By order of the Islamic Republic of Iran on September 22, 2022, daylight saving time (DST) will no longer be observed and the republic will remain on Iran Standard Time UTC+03:30.</li><li>After the Windows Monthly Rollup dated on or after November 8, 2022, is installed, Kerberos constrained delegation (KCD) fails with the error message KRB_AP_ERR_MODIFIED on Read/Write Domain Controllers.</li></ul>	<a href="#">KB5026413</a>	1
2023-05 Security only Quality update for Windows Embedded Standard 7 for x86-based Systems	This update makes improvements for the following issues: <ul style="list-style-type: none"><li>By order of the Islamic Republic of Iran on September 22, 2022, daylight saving time (DST) will no longer be observed and the republic will remain on Iran Standard Time UTC+03:30.</li><li>After the Windows Security-only update dated November 8, 2022, is installed, Kerberos constrained delegation (KCD) fails with the error message KRB_AP_ERR_MODIFIED on Read/Write Domain Controllers.</li></ul>	<a href="#">KB5026426</a>	1

Note:-

1. Due to environment issue patches were unable to be validated this month on device C2S1.

BD, Franklin Lakes, NJ, 07417, U.S.  
201.847.6800

[bd.com](#)

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

