

Security Patches: BD Totalys™ DataLink

March 2026

BD has validated patches from Microsoft® that have been identified as critical or security related to December 2025. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements. Customers should note that these patches are only applicable to the Windows IOT10 1809 build.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing Stack Update for Windows 10 1809	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed prior to all other updates
Cumulative update for Windows 10 1809	This update addresses several security issues for the Windows operating system.	KB5071544	
Cumulative Update for .NET Framework 3.5 and 4.7.2 for Windows 10 1809	This security update includes security and cumulative reliability improvements in .NET Framework 3.5 and 4.7.2.	KB5066143	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

