

Security Patches: BD Viper™LT

March 2026

BD has identified patches from Microsoft® that have been identified as critical or security related through February 2026. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Note: KB5075903 is Servicing Stack Update (servicing stack version 17763.8381) was released February 10, 2026. It is bundled with the February 2026 cumulative update KB5075904.

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed first.
Cumulative update for windows 10 Version 1809	This update addresses security issues of the operating system.	kb5075904	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

