Security Patches: BD Viper™LT

September 2025

BD has identified patches from Microsoft® that have been identified as critical or security related through June 2025. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Note: The current security updates are not recommended to be deployed on any Windows XP reader configurations.

BD, Franklin Lakes, NJ, 07417, U.S. 201.847.6800







Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing Stack Update	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed first.
Windows 10 1809 Security update for SQL Server 2016	This update addresses security issues of the operating system.	KB5014351	
Windows 10 1809 Cumulative update for .NET Framework 3.5 and 4.8.	This update addresses security bypass and elevation of privilege vulnerabilities.	<u>KB5049615</u>	
Cumulative Update for Windows 10 Version 1809 for x64-based Systems	This update lists the security issues and quality improvements included in this security update	<u>KB5060351</u>	
Security Update for Microsoft ODBC Driver 17 for SQL Server	This driver updates addresses security issues for the SQL Server database.	<u>KB5037570</u>	
Security Update for Microsoft OLE DB Driver for SQL Server	This driver updates addresses security issues for the SQL Server database.	KB5040711	

BD, Franklin Lakes, NJ, 07417, U.S. 201.847.6800

bd.com