

Security Patches: BD Totalys™ DataLink

June 2023

BD has identified patches from Microsoft® that have been identified as critical or security related from January to April 2023. These patches were not found to adversely affect BD products and will be applied according to customers' service agreements.

Customers that maintain patches independent of BD automated delivery should ensure the validated patches are installed on their BD systems as the acting responsible entity in order to maintain the correct security posture of the system(s)

Microsoft® patches

Patch name	Description	Patch ID	Notes
Servicing stack update for Windows 10 1809	This update makes quality improvement to the servicing stack, which is the component that installs Windows updates.	KB5005112	This update must be installed prior to all other updates
Security update for OS Build 17763.4131	This security update addresses several issues related registry size, LSASS, AD, and DCOM hardening.	KB5023702	
Cumulative Security update for .NET Framework 3.5 and 4.7.2	Includes cumulative reliability improvements in .NET framework 3.5 and 4.7.2	KB5022511	

BD, Franklin Lakes, NJ, 07417, U.S.
201.847.6800

bd.com

BD and the BD Logo are trademarks of Becton, Dickinson and Company or its affiliates. © 2022 BD. All rights reserved.

